

ETON'S PRIORITY ISSUES TRACKER			Prepared by Eton Action List Group			New Issue Reported		
Produced/Updated: 8 Jan 24			30+ days on to RBWM List	Outstanding 60+ days	Outstanding 90+ days	Completed		
Ref	Date reported	Details	Reference No.	Issue Raised By	Location	Status	Action Taken	Date Resolved
RBWM Maintenance & General Issues								
EN21/46M	07/06/2021	Repaint height barrier MLCP	24677-102905	EAG	Eton Ct.		Will be done in this financial year. Was not done. May be done end of financial year . Now informed this is in the 2023-4 capital budget. Will be done Oct 23- Mar 24 Will not now be done due to financial situation. Suggested this should be maintenance not capital.	
EN22/12M	05/02/2022	Bed on approach to Windsor Bridge needs planting up after being extended	24677-193932	EAG	Windsor Bridge Approach	Awaiting Planting	Reported as it has a direct effect on the approach to Eton. Will be planted over winter 22/23. Reported again 7 Mar. 23 - 24677-328122	
EN22/28M	04/04/2022	Meadow Lane adjacent to 6-space car parking - fence broken	24677-214045	EAG	Meadow Lane		Old fencing cleared. Brought up at Tivoli meeting with RBWM Officer 29 Nov.	
EN22/49M	04/07/2022	Graffiti on PSPO sign on Meadow Lane opposite SML junction	24677-246413	EAG	Meadow Lane		RBWM will not clean as not considered offensive. We believe this leads to a deterioration of the streetscape	
EN22/50M	04/07/2022	Graffiti on Vodafone box near Pockocks Lane on Slough Road	24677-246415	EAG	Slough Road		Passed to Vodafone to remove. Failure to remove leads to a deterioration of the streetscape.	
EN23/05M	07/01/2023	Pavement Survey	24677-308864	EAG	High St.		The pavement survey carried out last year has been updated on the 3 Jan 24 and submitted to Town Council and RBWM Councillors. RBWM will not do repairs unless they consider it a safety issue however this leads to a deterioration of the streetscape.	
EN23/10M	07/03/2023	Poor condition of shrub bed on approach to Windsor Bridge	24677-328122	EAG	Bridge approach		Re-reporting of 24677-193932 5/2/22. This was supposed to have been planted up during winter 2022/3	
EN23/11M	07/03/2022	Poor condition of Shrub bed by step up to bridge from Thames Side	24677-328137	EAG	Thames Side		Re-reporting of 24677-193931	
EN23/12M	07/03/2023	Poor condition of paintwork on railings and street lamps in Thames Side	24677-328144	EAG	Thames Side		Re-reporting of 24677-193931 - Mar.23 We have been told it is now added to work programme	
EN23/24M	04/04/2023	Eton sign at Keates Lane junction reflective surface damaged/deteriorated.	24677-338452	EAG	Slough Road		28 days - 8 June 23 not done	
EN23/28M	16/04/2023	South Meadow Lane - parking bay nearest Meadow Lane double yellow line - no termination markings	24677-342229	EAG	South Meadow Lane			
EN23/34M	08/06/2023	MLCP/Eton Ct. Hedge requires cutting	24677-364285	EAG	Eton Ct.		Roadside cut but not top and car park side. 8 Jan 24 - Hedge has only partially been cut due to parked cars.	
EN23/39M	08/07/2023	Acco Drainage Channels & Gullies need attention - some Acco channels blocked completely	24677-376139	EAG	High St.			
EN23/42M	27/07/2023	Shrub requiring cutting back as it is covering Eton Sign on Slough Rd prior to Pockocks Lane	24677-383388	EAG	Slough Rd.			
EN23/46M	05/09/2023	Ivy growing over wall from Turks Head Court into Eton ct. car park	24677-397762	EAG	Eton Ct.		Partially cut but not sufficiently	
EN23/47M	05/09/2023	Weeds overhanging path by Meadow Lane resident parking	24677-397767	EAG	Meadow Lane			

EN23/48M	05/09/2023	Weeds at base of Eton ct. hedge overhanging path	24677-397770	EAG	Eton Ct.			
EN23/50M	19/09/2023	Bus stop leaning	24677-407880	EAG	High St.		RBWM will not do this as not considered safety issue	
EN23/54M	12/10/2023	Acco Drains blocked in Eton Ct. Car Park	24677-410894	EAG	Eton Ct.			
EN23/55M	07/11/2023	Roads require sweeping - ML & SML	24677-419095	EAG	Meadow Lane and South Meadow Lane			
EN23/58M	04/12/2023	Graffiti on telecom boxes in High St. and Brocas Street adjacent to The George PH.	24677-429046	EAG	High St & Brocas St.			
EN23/59M	08/12/2023	Doule light Eton Ct/MLCP boundary out again	24677-431137	EAG	Eton Ct.			
EN24/01M	08/01/2024	Light iut on SW corner of Windsor Bridge	24677-439171	EAG	Windsor Bridge			
EN24/02M	08/01/2024	Balustrade lighting on Windsor Bridge about 40% failed	24677-439176	EAG	Windsor Bridge			
EN24/3M	08/01/2024	Protruding services cover outside 91 High St.	24677-439296	EAG	High St.			
Other Maintenance & General Issues								
		<b>Projects</b>						
EN65P	01/08/2018	Free Wi Fi in Eton		Neighbourh'd Plan Project	High St.	Researching	Proposal to put free wi-Fi along Eton High Street	
EN18/2P	01/08/2018	Elexctric Car Charging Points		Neighbourh'd Plan Project	Meadow Lane Car Park	Progressing	Proposal to electric car charging points in spaces adjacent to lamp posts	
EN18/4P	01/05/2019	Make new pedestrian access between MLCP and Eton Court		EAG	Meadow Lane Car Pak	Progressing	To make a new pedestrian access between both old and new sections of Meadow Lane car park and Eton Court. Plans received and agreed. Awaiting finance	
EN19/2P	18/10/2019	Review South Meadow Lane/ Meadow Lane. Narrowness/ large vehicles/ high kerbs		Various	Eton	Unresolved	Meeting held with ETC, Residents Groups, Ward Cllrs and Lead Member for Infrastructure 4/11/19. Actions: RBWM to produce options paper for emergency roadworks,planned roadworks and normal operation. Awaiting follow up meeting. No date has been arranged yet. Proposals are being worked on to width limit vehicles entering both lanes. Only Action taken was to put up "Not Suitable for HGVs" signs at either end.	June.22
EN19/7P Preeviously EN44M	10/01/2020	Electrical upgrade Eton High Street			High St.	Partially complete	An electrical survey carried out in 2019 found that much of the High St. street and sign lighting circuits are non-compliant and require upgrading. Will be carried out over 2 years 2021/22 & 2022/23. Lamp satandards in place. Feb.22	
EN20/1P	10/01/2020	High St properties communication cabling upgrade			High St.		Along much of the High St. communicatio cables are draped along the fronts of building looking very untidy. Work is required to rationlaise and remove cabling wherever possible.	
EN20/2P	31/03/2020	Light standards in Somerville Road require painting/replacement	HIG018762	EAG	Somerville Road		Originally reported as maintenance (EN20/15M) but transferred to project as replacement required.	
EN20/3P	31/03/2020	Light standards in Broken Furlong require painting/replacement	HIG018763	EAG	Broken Furlong		Originally reported as maintenance (EN20/16M) but transferred to project as replacement required.	